

五權國小-水塔清洗照片 施工日：111/8/23



廚房旁 1-洗前 1



廚房旁 1-洗前 2



廚房旁 1-洗後 1



廚房旁 1-洗後 2



廚房旁 2-洗前 1



廚房旁 2-洗前 2



廚房旁 2-洗後 1



廚房旁 2-洗後 2



五權國小-水塔清洗照片 施工日：111/8/23



廚房旁 3-洗前 1



廚房旁 3-洗前 2




廚房旁 3-洗後 1



廚房旁 3-洗後 2



廚房上 4-洗前 1



廚房上 4-洗前 2



廚房上 4-洗後 1




廚房上 4-洗後 2



五權國小-水塔清洗照片 施工日：111/8/23



廚房上 5-洗前 1



廚房上 5-洗前 2




廚房上 5-洗後 1



廚房上 5-洗後 2



廚房上 6-洗前 1



廚房上 6-洗前 2



廚房上 6-洗後 1



廚房上 6-洗後 2



五權國小-水塔清洗照片 施工日：111/8/23



廚房上7-洗前1



廚房上7-洗前2



廚房上7-洗後1



廚房上7-洗後2



至真樓8-洗前1



至真樓8-洗前2



至真樓8-洗後1



至真樓8-洗後2



五權國小-水塔清洗照片 施工日：111/8/23



至真樓 9-洗前 1



至真樓 9-洗前 2




至真樓 9-洗後 1



至真樓 9-洗後 2




至美樓 10-洗前 1



至美樓 10-洗前 2



至美樓 10-洗後 1




至美樓 10-洗後 2



五權國小-水塔清洗照片 施工日：111/8/23



至美樓 11-洗前 1



至美樓 11-洗前 2



至美樓 11-洗後 1



至美樓 11-洗後 2




至美樓 12-洗前 1



至美樓 12-洗前 2



至美樓 12-洗後 1



至美樓 12-洗後 2



五權國小-水塔清洗照片 施工日：111/8/23




至美樓 13-洗前 1



至美樓 13-洗前 2



至美樓 13-洗後 1



至美樓 13-洗後 2



至美樓 14-洗前 1



至美樓 14-洗前 2



至美樓 14-洗後 1



至美樓 14-洗後 2